


IRONY - STUDY DESK

Assembly Instruction - 1




NO	W	x	L	x	H
01	273	x	582	x	18
02	334	x	544	x	18
03	334	x	273	x	18
04	273	x	582	x	18
05	332	x	582	x	18
06	414	x	564	x	18
07	314	x	564	x	18
08	1196	x	332	x	18
09	1196	x	458	x	18
10	1196	x	154	x	18
12	1214	x	90	x	18
13	289	x	140	x	18
14	299	x	454	x	8
15	364	x	270	x	18
16	369	x	140	x	18
17	379	x	454	x	8
18	450	x	239	x	18
19	258	x	104	x	50
22	104	x	70	x	104
25	104	x	104	x	86
71	450	x	160	x	18
72	450	x	160	x	18

IRONY - STUDY DESK

(V02)

Assembly Instruction - 2









NO	W	x	L	x	H
01	273	x	582	x	18
02	334	x	544	x	18
03	334	x	273	x	18
04	273	x	582	x	18
05	332	x	582	x	18
06	414	x	564	x	18
07	314	x	564	x	18
08	1196	x	332	x	18
09	1196	x	458	x	18
10	1196	x	154	x	18
12	1214	x	90	x	18
13	289	x	140	x	18
14	299	x	454	x	8
15	364	x	270	x	18
16	369	x	140	x	18
17	379	x	454	x	8
18	450	x	239	x	18
19	258	x	104	x	50
22	104	x	70	x	104
25	104	x	104	x	86
71	450	x	160	x	18
72	450	x	160	x	18

Accessory	A	B	C	D	E	F	G	H	J	K	L	M
Quantity	40	44	4	8	3	10	8	4	2	2	1	44







IRONY - STUDY DESK^(V02)

Assembly Instruction - 3



IRONY - STUDY DESK_(V02)

Assembly Instruction - 4



IRONY - STUDY DESK (V02)

Assembly Instruction - 5

Diagram illustrating the assembly of the desk frame, showing the connection of parts 13, 14, 15, 72, and K using screws D, H, E, and J.

Parts shown: 13, 14, 15, 72, K, D, H, E, J.

